

SECTION 1

1.2 Results Summary

Student Health Center

ACM SURVEY RESULTS

The following homogeneous building material types were sampled as part of this survey conducted May 29, 2003. Results are summarized in the table below:

MTL #	MATERIAL DESCRIPTION	LOCATION	F/NF ¹	COND. ²	% ACM	# SAMP.	QUANTITY
01	1' x 1' White fissured ceiling tile	Main entry (1000), 1204, 1223, 1225, stairway, hallway next to room 0105	F	Good	ND	3	N/A
02	12" x 12" Tan floor tile/mastic	Throughout except main entry, men's restroom 1, women's restroom 1, 1145, 1143, 1141, 1139, 1137, 1135, 1133, 1129, 1131, 1125, 1119, 1108, 1108a, 1108b, 1108c, 1108d, 1104, 1190a, 1201, 1203, 1205, 1204, 1207, 1209, 1211, 1225, 0109, 0115, 0101, 0105a	NF	Good	Floor tile = 4% Mastic = 5%	3	17,000 SF
03	6" Brown cove base/mastic	Throughout except main entry (1000), men's restroom, women's restroom, 1145, 1143, 1139, 1141, 1137, 1135, 1133, 1129, 1131, 1119, 1108, 1108a, 1108b, 1108c, 1108d, 1104, 1190a, 1201, 1203, 1205, 1204, 1207, 1209, 1211.	NF	Good	Cove base = ND Mastic = 4%	3	3,000 SF
04	6" Black cove base/mastic	Main entry (1000) 1145, 1143, 1141, 1139, 1137, 1135, 1133, 1129, 1131, 1201, 1203, 1205, 1204, 1207, 1209, 1211, 1225 **Removed in 2009 – Main Entry men's and women's room.	NF	Good	Cove base = ND Mastic = ND	3	N/A
05	4" Brown cove base/mastic	1114a, 1111, 1160, 1190e, 1166, 1223	NF	Good	Cove base = ND Mastic = 4%	3	130 SF
06	Drywall (white) Joint compound*	Throughout except 1108, 1108a, 1108b, 1108c, 1108d, 1104, 1190a. **Removed in 2009 – Main Entry men's and women's room.	F	Good	Drywall = ND JC = <1%	3	60,000 SF
07	Blue carpet mastic	Main entry (1000), 1145, 1143, 1141, 1139, 1137, 1135, 1133, 1129, 1131, 1201, 1203, 1205, 1204, 1207, 1209, 1211, 1225	NF	Good	ND	3	N/A
08	Drywall (blue) Joint compound*	1102, 1156, 1143, 1141, 1139, 1137, 1135, 1133, 1129, 1166, 1218, 1221	F	Good	Drywall = ND JC = <1%	3	6,500 SF
09	1' x 1' White pinhole ceiling tile	1118, 1118a, 1114, 1114a, 1108	F	Good	ND	3	N/A
10	Drywall (pink) Joint compound*	1173, 1163, 1161, 1159, 1114, 1160, 1154, 1162	F	Good	Drywall = ND JC = <1%	3	5,000 SF
11	Drywall (green) Joint compound*	Stairway, hallway next to room 0105	F	Good	Drywall = ND JC = 2%	3	1,000 SF
12	6" Brown cove base/mastic	Basement, hallway next to room 0105, stairway	NF	Good	Cove base = ND Mastic = 3%	3	70 SF
13	Drywall (white) Joint compound*	0105, 0109, 0115	F	Good	Drywall = ND JC = 2%	3	3,000 SF
14	Fire stop	0101, 0115	NF	Good	ND	3	N/A
15	Vibration joint cloth/mastic	Main entry, stairway, 0115, 1204, 1166	NF	Good	Cloth = ND Mastic = ND	3	N/A
16	Sink undercoating	1108a, 1108b, 1108c, 1108d, 1190e, 1223	F	Good	10%	3	25 SF

MTL #	MATERIAL DESCRIPTION	LOCATION	F/NF ¹	COND. ²	% ACM	# SAMP.	QUANTITY
17	Hard plaster (pink)	1108a, 1108b, 1108c, 1108d	NF	Good	ND	3	N/A
18	Hard plaster (pink)	1105, 1108, 1108a, 1108b, 1108c, 1108d, 1160, 1104, 1190a, 1190c, 1154, 1148	NF	Good	ND	3	N/A
19	Drywall (yellow) Joint compound*	1114a	F	Good	Drywall = ND JC = 2%	3	1,500 SF
20	Flooring material	Stairway	NF	Good	ND	3	N/A
21	TSI Elbow insulation	1218, main entry	F	Good	ND	3	N/A
22	Mastic under 1' x 1' white pinhole ceiling panel	1118, 1118a, 1114., 1114a, 1108	NF	Good	ND	3	N/A

Assumed Materials

	Fire doors/frames	Room 1000, 0105, main entry	NF	Good	Assumed	0	2
	Grout (ceramic tile)	1119, 1117, 1115, women's restroom, 1118a, 1108, 1108a, 1108b, 1108c, 1108d, 1104, 1190a, men's restroom, 1215 **Removed in 2009 – Main Entry men's and women's room.	NF	Good	Assumed	0	2,400 SF
	Vapor barriers	1119, 1117, 1115, women's restroom, 1118a, 1108, 1108a, 1108b, 1108c, 1108d, 1104, 1190a, men's restroom, 1215	NF	Good	Assumed	0	2,400 SF

** Reviewed Jan. 2009 – note the changes in the Lobby men's and women's rooms.

¹ F = Friable; NF = Non-friable

Friability is further defined in section 4

² Cond. = Condition Of Materials

Either good, fair or poor

* Bay Area Air Quality Management District – identifies this material as friable for renovation and disposal purposes.